

**EPS SSR-6**

**POWER BUS LOSS: RPDA Z14B (Includes RPCMs Z14B A and B)**

ACTION	EQUIP/FUNCTION LOST	CREW INDICATION	NOTES
<p>Power On PCU PCS Z1: EPS</p> <div style="border: 1px solid black; padding: 2px; width: fit-content; margin: 10px auto;">RPCM Z13B B</div> <p>sel        RPC 15 cmd    Close √Position - CI</p>	<p>RPCM Z14B A (Type VI) RPCM Z14B B (Type V)</p> <hr/> <p>1 SPDA Z13B Htr SPDA Z14B Htr CMG 2 Ext Htr CMG 3 Ext Htr PCU 1 Htr DDCU Z13B Htr 2 DDCU Z14B Htr 1 KU-Band SGTRC Htr KU-Band SGANT Htr S-Band BSP 2 Htr S-Band SASA 2 Htr EEATCS Non-Op Htr B-1</p> <hr/> <p>CMG 1 CMG 4</p> <hr/> <p>PCU 2</p>	<p><b>Caution Messages:</b></p> <p><b>Advisory Messages:</b></p> <p>RPCM Z14B_A Loss of Comm - Z1 RPCM Z14B_B Loss of Comm - Z1</p> <p><b>Telemetry:</b></p> <p>PCS Z1: EPS</p> <div style="border: 1px solid black; padding: 2px; width: fit-content; margin: 5px auto;">Z1: EPS</div> <p>RPCM Z14B A - not Active RPCM Z14B B - not Active</p>	<p>① KU-Band, S-Band, EEATCS, CMG, and PCU heaters are not redundant, possible loss of equipment. PCU is powered to provide some heat.</p>